

REFERENCES.

- A—Hopper.
- B—Feeding Tray.
- C—Feed Motion Bracket.
- D—Hopper Box.
- E—Outer Casing.
- F—Grinding Path.
- G—Disc.
- H—Clutch.
- I—Indiarubber Buffer.
- J—Ball.
- K—Main Shaft.
- L—Screen.
- M—Discharge Spout.
- N—Driving Pulley.
- O—Oil Catcher.




FIG. 60.—VERTICAL SECTION.

REFERENCES (continued).

- c—Feed Motion Pulley.
- c¹— " " Link.
- c²— " " Universal Joint.
- c³— " " Regulator.
- d—Main Water Supply.
- d¹—Extra " "
- d²—Screen " "
- l—Baffle Protecting Screen.
- l¹—Wire (or pierced Copper Plate) Gauze.
- l²—Splash Plate.
- l³—Water Bearing.
- n—Loose Pulleys




FIG. 61.—ELEVATION.




FIG. 62.—TRANSVERSE SECTION.

The Globe Wet-Crushing (or "Cyclops") Mill.